

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	Dholbaja Middle School to Kasma Pubwan tal Hea		
Hazards:	Flood/Rain	Discrete Level	
Division:	District:	Actual Length (in km): 1.534	
Damage Length (in km): 0.186	Damages Location/Chainage: Photo at school		
Name of Scheme/Programme:	PMUSY		
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)	S	
a)	Condition of Surfacing	S	

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N/A

Description of observation :

e)	Compaction of flanks/ slope & rain
Description of observation: E/W not done in flank	
2	Cross Drainage Structure
a)	Condition of head walls in Hume pipe culverts
b)	Condition of Vent Clearance
c)	Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: work found satisfactory. Boulder pitching work in slop was going on.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: KUMAR RAKESH

Designation: कमीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

21/7/21
HC

(Signature)

02-07-21