

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	Tos to Masukia		
Hazards	Flood/Rain		
Division:	Madhubani	District:	Madhubani
Actual Length (in km):	3.790		
Damage Length (in km):	0.295	Damages Location/Chainage:	Photo attached
Name of Scheme/Programme:	PMUSY		
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameter's to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)	U	
a)	Condition of Surfacing	U	

Description of observation : Laying and rolling temp. not maintained.

b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N/A

Description of observation :

e)	Compaction of flanks/ slope & rain.	
Description of observation: No E/W done in flanks. U		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N/A
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any: Laying and rolling temp. was not maintained.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

Recd
21/7/21
4E