

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Khajauli to Harsiswara</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Madhubani</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>5.00</u>
Damage Length (in km): <u>0.298</u>	Damages Location/Chainage:	
Name of Scheme/Programme: <u>PMUSY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>S</u>
a)	Condition of Surfacing	<u>S</u>

Description of observation :

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
----	---	----------

Description of observation :

c)	Quality of Construction Material Used	<u>S</u>
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>N/A</u>
----	---	------------

Description of observation :

e)	Compaction of (banks/ slope & rain)	<u>-</u>
----	-------------------------------------	----------

Description of observation :

2	Cross Drainage Structure
a)	Condition of head walls in Hume pipe culverts
b)	Condition of Vent Clearance
c)	Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: Work found to have been done properly.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

21/7/21
42

(Signature)

02.07.21