

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Lamipur to NH105</u>		
Hazards: <u>Flood/Rain</u>		
Division:	District:	Actual Length (in km): <u>4.800</u>
Damage Length (in km): <u>0.705</u>	Damages Location/Chainage: <u>Photo attached</u>	
Name of Scheme/Programme: <u>old MMWSY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>U</u>
a)	Condition of Surfacing	<u>U</u>
Description of observation : <u>Laying and rolling temp. of</u> <u>MSS not maintained. Compaction poor</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>N/A</u>
Description of observation :		
e)	Compaction of flanks/ slope & rain	<u>S</u>
Description of observation:		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	<u>N/A</u>
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Laying and rolling temp. not</u> <u>maintained. Compaction poor in MSS.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

03.07.21

31/7/21
4E