

प्रमाणित किया जाता है कि दुर्गावती
पुरतः से कुल 100 (एक सौ) पन्ने
हैं जो M/R (3054) दुर्गावती
ककरैत रोड से निरोजपुर तक कार्य
का मापी लेने हेतु श्रीनिवास चौधरी
सहायक अभियंता कार्यालय कांठार
दुर्गावती के नाम से निर्गमित किया
जाता है।


Executive Engineer
R.W.D. Work Div. Mohania
20/8/20

Revised to Sri Satendra Prasad
Lal J. E. Singhwadi.
@Rouder
20/8/20
A.E.

M/R (3054)

Sch. XLV—Form No. 134

श्रीनिवास चौधरी सहायक अभियंता
कार्य प्रभाग दुर्गावती
कार्य- दुर्गावती ककरैत रोड से निरोजपुर
संवेदक- M/S विजय कुमार सिंह
Ag. No- 29 MBD/20-21

Measurement Book
No. **460**

Name of Officer _____

Date of first entry _____

Date of last entry _____

Name to work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Repairing of Road					
from Durganti Karmait Road to					
Teraspur under 30.54 mR.					
Agency. m/s Brijendra Kumar Singh					
Village & P.O. Masaulha Dist. Kaimur					
Ag No. 29 MB 20/2020-21					
Date of start 22.5.2020					
Date of completion 21.2.2021					

Rate 0.516 Blm					
Date from 02/11/2020					
Item					
1/1 clay and 9/10 mud					
	2x	10	30w	1-w	600w
	2	1	21w	1-w	42w
	2	5	30w	0-40	270w
	2x	9	30w	1-w	540w
	2x	1	3w	1-w	6w
					1458w
D. 1458 Hbl					

Continuation

4871604-
 48, 42, 91320

Sch. XLV—Form No. 134

12

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Depth of soil below					
Sign level					50000-0
4921604-					335, 560m
					49, 42, 913-0
					49, 28, 473m
Depth of soil below					25, 209-0
					25, 135m
Depth of soil below					49, 42, 913-0
meas. m. B.					49, 03, 338
By 130					43, 09, 058
					608646-0
					5, 94, 280m
					587446-
Sum					
18/5/21					

Material at hand. 4P 10 Dali

- (1) E/W - 632.2m
- (2) Metal - 25.53m
- (3) Sand. 365.8m
- (4) Chalk - 709.6m

Sum
 18/5/21
 82

Continuation