

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *Sonubliya Dhala to Lambhari Dhala*

Hazards

Flood/Rain *Flood*

Division: *Gopalganj-2*

District: *Gopalganj*

Actual Length (in km): *2.0*

Damage Length (in km): *Approx. 0.200*

Damages Location/Chainage: *Approx 1.10 to 1.30*

Name of Scheme/Programme:

Old Scheme

Status of Project:

Under Agreement/Out of Agreement *Out of Agreement*

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/I)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

Description of observation:

Scope work not done till the time of inspection.

b)

Adequate Thickness of pavement layers constructed

Description of observation:

In approx 0.20 km length only pot patch work with GSBG II and WBMG III work done.

c)

Quality of Construction Material Used

Description of observation:

Quality of WBMG III material is satisfactory

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation:

1

e)

Compaction of flanks/ slope & raincuts

Description of observation:

No rain cuts in flanks

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

clear

Description of observation of CD works:

Remark if any:

Surface work not done.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer:

Rana Brown Kumar Singh

Designation:

Executive Engineer.

03.03.2021
(Signature)