

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *Pekki more to Khajuhatti*
 Hazards: *Flood/Rain Flood*
 Division: *Gopalganj - 2* District: *Gopalganj* Actual Length (in km): *3.5 km*
 Damage Length (in km): *Approx 0.500* Damages Location/Chainage: *Approx 2nd km to 640 2.10*
 Name of Scheme/Programme: *PMGSY*

Status of Project: *Under Agreement/Out of Agreement* *Out of Agreement*

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<i>S</i>

Description of observation : *In Approx 500m length of the road, 20mm MSS work done on the surface.*

b)	Adequate Thickness of pavement layers constructed	
----	---	--

Description of observation : *Below MSS work put patch work with GSB Gr II and WBM Gr III done.*

c)	Quality of Construction Material Used	
----	---------------------------------------	--

Description of observation : *Quality of MSS material is Satisfactory.*

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
----	---	--

Description of observation : *No undulation in Surface.*

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation : *No rain cuts in flanks.*

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	<i>OK</i>
----	---	-----------

b)	Condition of Vent Clearance	<i>Yes</i>
----	-----------------------------	------------

c)	Condition of railings/Slab/approach for Bridges	<i>-</i>
----	---	----------

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer:

Designation:

(Signature)