

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>L031, T02 to Deorikhash</u>		Flood/Rain	
Hazards	Division: <u>Kishanganj 1</u>	District: <u>Kishanganj</u>	Actual Length (in km): <u>3.50 km</u>
Damage Length (in km): <u>0.300</u>	Damages Location/Chainage: <u>1.20</u>		
Name of Scheme/Programme: <u>FDR</u>			
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		
a)	Condition of Surfacing		<u>S</u>
Description of observation : <u>Good condition</u>			
b)	Adequate Thickness of pavement layers constructed		<u>S</u>
Description of observation : <u>M ss. 20mm thickness</u>			
c)	Quality of Construction Material Used		<u>S</u>
Description of observation : <u>Satisfactory.</u>			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		<u>S</u>
Description of observation : <u>No undulation</u>			
e)	Compaction of flanks/ slope & raincuts		
Description of observation : <u>in blank, Earth work done Partially. A few raincut also banded; Need to be repaired</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works : <u>No Provision</u>			
Remark if any: <u>Earth work in blank to be needed - At 1.35 km chainage. As per site condition, 50m span R.C.C Bridge is needed. Due to water logging in diversion, and short of length could not measured</u>			
Overall Rating			
Satisfactory (S) / Unsatisfactory (U)			<u>Satisfactory</u>

Name of Officer: Mahesh Pd Gupta
 Designation: EE, RWD, Regionalles
Purnea

03/07/2024
 (Signature)