

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>L031-For Kharra to Suiya Harijan Tola</u>		
Hazards: Flood/Rain		
Division: <u>Kishanganj 1</u>	District: <u>Kishanganj</u>	Actual Length (in km): <u>1.970</u>
Damage Length (in km): <u>0.200</u>	Damages Location/Chainage: <u>0.8</u>	
Name of Scheme/Programme: <u>FDR</u>		
Status of Project: Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>U</u>
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>Satisfactory, M.SS - 20mm thickness</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Satisfactory</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>U</u>
Description of observation : <u>both Edge of BT work damaged in 50m length due to be not done proper Compaction in flanks.</u>		
e)	Compaction of flanks/ slope & raincuts	<u>U</u>
Description of observation : <u>NO Proper Compaction of flank & side slope not Maintained. Needs to be repaired</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>BT work of both edge of Road damaged in 50m length. Earth work in flank not done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer: Mahesh Pd Gupta

Designation: EE, RWD, Regional Lab -
Purnea

03/07/2017
(Signature)