

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Mohammadpur to Chak Feroz Road</u>		
Hazards		Flood/Rain
Division: <u>Muzaffarpur-1</u>	District: <u>Muzaffarpur</u>	Actual Length (in km): <u>2.800</u>
Damage Length (in km): <u>0.230</u>	+ Damages Location/Chainage: <u>1.150 KM - 1.210 KM, 1.450 KM - 1.570 KM</u> <u>2006 KM - 2056 KM</u>	
Name of Scheme/Programme:		
Status of Project: Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	—
a)	Condition of Surfacing	U
Description of observation : <u>Permanent Restoration work just started —</u> <u>material of WBM Gr III laid on site But rolling-</u> <u>to be done, so measurement has been not taken</u>		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation : <u>work in progress But not measurable.</u>		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	N.A.
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Remark if any: <u>Permanent Restoration work just started, Material of</u> <u>WBM Gr III laid on site But rolling to be done, so measure-</u> <u>ment has been not taken.</u>		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer: Ram Kumar Mishra

Designation: EE, R. Lab, Gulzarbag, Patna

S
03/07/2021

1/2
03/07/2021
(Signature)