

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Sarvodaya High School Vishnupur Baghnagar To Sonar Tola Jhatkauri</u>		
Hazards	Flood/Rain	
Division : <u>Muzaffarpur-1</u>	District: <u>Muzaffarpur</u>	Actual Length (in km): <u>2.110</u>
Damage Length (in km): <u>0.220</u>	Damages Location/Chainage: <u>1.610KM-1.635KM, 1.740KM-1.691KM</u> <u>1.844-2.090KM</u>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement ☒ Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	—
a)	Condition of Surfacing	U
Description of observation : <u>Permanent Restoration work just started But not —</u> <u>measurable.</u>		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship. etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	N.A.
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
C)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Remark if any: <u>Permanent Restoration work just started But not measurable.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab Gulzarbagh, Patna

03/07/2021

03/07/2021