

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme:	Islampur to Sahdeva	
Hazards	Flood/Rain	
Division :	Raxaul	District: Motihari Actual Length (in km): 1.000
Damage Length (in km):	1.000	Damages Location/Chainage:
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	
Description of observation :		
No work done		
b)	Adequate Thickness of pavement layers constructed	
Description of observation :		
No work done		
c)	Quality of Construction Material Used	
Description of observation :		
No work done		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	
Description of observation :		
No work done		
e)	Compaction of flanks/ slope & raincuts	
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any:	In 1000 m length BT to be done as per estimate. But, No work done.	

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	Unsatisfactory
---------------------------------------	----------------

Name of Officer: Mahesh Pd Gupta.
 Designation: EE, Regional Lab., RWD
 Purnea

(Signature)
 10/02/2017