

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Sariswa Market to MR Road		
Hazards Flood/Rain		
Division : Beta District: West Champaran Actual Length (in km): 1.200 km		
Damage Length (in km): 0.187 km Damages Location/Chainage: 0.600 km, 1.00 km		
Name of Scheme/Programme: FDR (3054)		
Status of Project: Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	
1.	Pavement (BT/CC) BT	
a)	Condition of Surfacing	
Remarks : (S/U)		
S		
Description of observation : MSS work is in good condition		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : CrSB - 200 mm WBM Crs-LL - 75 mm MSS - 20 mm		
c)	Quality of Construction Material Used	
Description of observation : Good quality material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	
N.A.		
e)	Compaction of flanks/ slope & raintcuts	
Description of observation : Flank work is in good condition		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works : N.A.		
Remark if any: Work is in good condition		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ratnesh Paswan

Designation: E.E.


 11/7/21
 (Signature)

E.E.