

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <i>Koirgawan to Rajpurpath and Pull Maramati Work.</i>		
Hazards	Flood/Rain	
Division: <i>Narkatiyaganj</i>	District: <i>West Champaran</i>	Actual Length (in km):
Damage Length (in km): <i>0.076</i>	Damages Location/Chainage:	
Name of Scheme/Programme:	<i>FDR</i>	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure <i>R. C. C. Culvert complete.</i>	
a)	Condition of head walls in Hume pipe culverts	'S'
b)	Condition of Vent Clearance	'S'
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works : <i>R. C. C. culvert complete and approach work is on going.</i>		
Remark if any: <i>R. C. C. culvert complete and approach work is on going.</i>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Sri Kant Prasad
Name of Officer:

Designation: *E-E*

SAS
10/7/21
A.E

AB
10/7/2021
(Signature)