

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Kashi Bandh to Kanauli

Hazards: Flood/Rain

Division: Supaul

District: Supaul

Damage Length (in km): 0.400

Actual Length (in km): 1.450 KM

Name of Scheme/Programme:

Damages Location/Chainage: 0.358KM - 0.500KM, 0.731KM - 0.879KM & 1.358KM - 1.418KM

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

CC

S

Description of observation :

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

c)

Quality of Construction Material Used

S

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

S

Description of observation :

e)

Compaction of flanks/ slope & raincuts

In Progress

Description of observation :

2

Cross Drainage Structure

N/A

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer: Ram Kumar Mishra

Designation: EE, R. Lab. Gulzarbag, Patna

10/07/2021

10/07/2021