

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Fulan Chowk to Palapuz Vda Harijan Tola Rajauri</u>		
Harazid	Flood/Rain	Flood
Division: <u>Bansoi</u>	District: <u>Katihar</u>	Actual Length (in km): <u>2.704</u>
Damage Length (in km): <u>0.410 km</u>	Damages Location/Chainage:	
Name of Scheme/Programme:		
Status of Project:		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	BT
a)	Condition of Surfacing	S
Description of observation :		
Surface found in good Condition.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
Adequate Thickness found.		
c)	Quality of Construction Material Used	S
Description of observation :		
Good quality of Material used.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation :		
NA		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation :		
found in good Condition.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	NA
b)	Condition of Vent Clearance	NA
c)	Condition of railings/Slab/approach for Bridges	NA
Description of observation of CD works :		
NA		
Remark if any:		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

Ch
11/7/21
(Signature)

Ch
11/7/21
E.E.