

## INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Chhardwali chowk to Chhardwali</u>		
Hazards	<u>Flood/Rain</u>	
Division: <u>Markatiyegang</u>	District: <u>West Champaran</u>	Actual Length (in km): <u>1.20</u>
Damage Length (in km): <u>0.04</u>	Damages Location/Chainage:	
Name of Scheme/Programme:	<u>FDR</u>	
Status of Project:	<input checked="" type="checkbox"/> Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	—
a)	Condition of Surfacing	—

Description of observation :

b)	Adequate Thickness of pavement layers constructed	—
----	---	---

Description of observation :

c)	Quality of Construction Material Used	—
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	—
----	--	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	---

Description of observation :

2	Cross Drainage Structure	S
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	S
c)	Condition of railings/Slab/approach for Bridges	—

Description of observation of CD works :  
One Rcc slab culvert abutment work is on going and 2nd Rcc slab culvert abutment work done but submerged in water due to flood.

Remark if any: At present time work is stopped due to flood.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Sri Kant Prasad  
 Name of Officer:

Designation: E.E.

13/07/21  
 A.E.

13/7/2021  
 (Signature)