


INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

(4)

Name of Scheme: Kadwa to Harijan Tola via Srivijaya Ginda ban Tak	
Name of District: Raasol	Flood/Rain Flood
Division: Raasol	District: Kathbar
Damage Length (in km): 0.769	Actual Length (in km): 0.769
Name of Scheme/Programme: MR-3054(FDR)	Location/ha/haage:
Status of Project: Under Agreement/Out of Agreement	Parameters to be Checked in Restoration work
Sr. No: 1	Pavement (BT/CC)
	Condition of Surfacing
Description of observation : BT Surface found in Good Condition.	
a)	BT
Remarks : (S/U)	
S	
Description of observation :	
b)	Adequate Thickness of pavement layers constructed
Description of observation :	
Adequate Thickness found	
S	
Description of observation :	
c)	Quality of Construction Material Used
Description of observation :	
Good quality of Material used	
S	
Description of observation :	
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.
Description of observation :	
NA	
Description of observation :	
e)	Compaction of flanks/ slope & raincuts
Description of observation :	
Found in good Condition	
S	
Description of observation of CD works :	
2	Cross Drainage Structure
a)	Condition of head walls in Hume pipe culverts
b)	Condition of Vent Clearance
c)	Condition of railings/Slab/Approach for Bridges
Description of observation of CD works :	
7	
Remarks if any:	
Overall Rating	
Satisfactory (S) / Unsatisfactory (U)	S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.


 12/7/21
 (Signature)