


INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Motihari Rukhi PWD Road to Sahni Tola.		
Hazards: Flood/Rain		
Division: Motihari	District: Purvi Champaran	Actual Length (in km): 3.20 km
Damage Length (in km): 0.180 km	Damages Location/Chainage: -	
Name of Scheme/Programme: FDR		
Status of Project: Under Agreement/Out of Agreement		Out of Agreement.
Parameters to be Checked in Restoration work		Remarks : (S/U)
Sr. No.		
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation : 20 MM Mix seal surface in Length 180m done.		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : 75 MM WBM Gr III in patches done 20 MM Mix seal surface in Length 180m done.		
c)	Quality of Construction Material Used	S
Description of observation : Good quality		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	-
Description of observation : No provision in the scheme .		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	-
c)	Condition of railings/Slab/approach for Bridges	-
Description of observation of CD works : No provision in the scheme .		
Remark if any: Restoration work completed.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ram Prabesh Saw
 Designation: T.A, RWD
 Work Circle Siwan


 (Signature)
 12/07/21
 AE