

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Boishakhwa to Sargatiya Path</u>		
Hazards	Flood/Rain	
Division : <u>Narkatiyaganj</u>	District: <u>West Champaran</u>	Actual Length (in km): <u>7.425</u>
Damage Length (in km): <u>0.029/0.048</u>	Damages Location/Chainage:	
Name of Scheme/Programme:	<u>FDR</u>	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation :		
b)	Adequate Thickness of pavement layers - constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	—
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Remark if any: <u>No any Works done due to flood.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Sri Kant Prasad

Name of Officer:

Designation: E.E.

21/11/21
A.E.

11/7/21
(Signature)