

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Jagannathpur Hachauri PWD Road to Unser Kotra Pith		
Hazards	Flood/Rain Flood	
Division: Mu3-East-2	District: Mu3a, Jharkhand	Actual Length (in km): 4.750
Damage Length (in km): 2.60	Damages Location/Chainage: 0 to 4.75 Km	
Name of Scheme/Programme: FDR 3054 ✓		
Status of Project: Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) BT	S
a)	Condition of Surfacing	S

Description of observation : Pots Patch Repairs

b)	Adequate Thickness of pavement layers constructed	S
Description of observation : C/SB gr. I - 100 mm WBM gr. III - 75 mm M.S.S. - 20 mm 195 mm		
c)	Quality of Construction Material Used	S

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A
----	---	-----

Description of observation :

e)	Compaction of flanks/ slope & raincuts	S
----	--	---

Description of observation :

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N.A
b)	Condition of Vent Clearance	N.A
c)	Condition of railings/Slab/approach for Bridges	N

Description of observation of CD works :

Remark if any: Damage part of Road Pots Patch Work done.

Overall Rating


Satisfactory (S) / Unsatisfactory (U)


Satisfactory

Name of Officer:

Bindu Rajak
Executive Engineer
R.W.D. Regional Laboratory
Dombhanga.

Designation:


M. E.


(Signature) 2/07/23