

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <i>Raxipatan PWD to Manjheli PWD road.</i>		
Hazards	Flood/Rain <i>Flood in 2020-21</i>	
Division : <i>Purnia</i>	District: <i>Purnia</i>	Actual Length (in km): <i>8.85</i>
Damage Length (in km): <i>0.015 approx.</i>	Damages Location/Chainage: <i>0.900 to 0.115 approx.</i>	
Name of Scheme/Programme:	<i>MR-3054</i>	
Status of Project:	Under Agreement/Out of Agreement <i>Out of Agreement</i>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<i>—</i>
Description of observation : <i>Surface work not done</i>		
b)	Adequate Thickness of pavement layers constructed	<i>U</i>
Description of observation : <i>Temporary Restoration work has been found done at breach point only. Approx 10m length of RT side is water logged.</i>		
c)	Quality of Construction Material Used	<i>—</i>
Description of observation : <i>—</i>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<i>—</i>
Description of observation : <i>—</i>		
e)	Compaction of flanks/ slope & raincuts	<i>U</i>
Description of observation : <i>Flanks are submerged by water.</i>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works : <i>—</i>		
Remark if any: <i>Temporary Restoration work done only. This road is in Tenders process under PMWSY phase -III in which provision of New culvert made.</i>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<i>Unsatisfactory (U)</i>
---------------------------------------	---------------------------

Name of Officer: *Ram Brown Kumar Singh.*
 Designation: *Executive Engineer*
RWD, Regional Laboratory Bhopalpur.

10.07.2021
 (Signature)