

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: NH-28 Gira Tola to Raja Ram Tak.

Hazards Flood/Rain

Division: Chakia District: Purvi Champaran Actual Length (in km): 2.155 km.

Damage Length (in km): 0.160 km Damages Location/Chainage:

Name of Scheme/Programme: FDR

Status of Project: Under Agreement/Out of Agreement Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing S

Description of observation : 20 MM Mix seal surface 160 metre length done

b) Adequate Thickness of pavement layers constructed S

Description of observation : 75mm WBM Gr III 8 20 MM Mix seal surface.

c) Quality of Construction Material Used S

Description of observation : Good quality

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. S

Description of observation :

e) Compaction of flanks/ slope & raincuts S

Description of observation :

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

No provision in the scheme.

Remark if any: Restoration work completed.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

Ram Prabesh Saw

Designation:

T.A. RWD

Work Circle Gwan

(Signature)