

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: NH-28 Semuapur Mela chowk to Anusuhit gate Tola.		
Hazards	Flood/Rain	
Division: Chakia	District: Darvi Champaran	Actual Length (in km): 2.639 km
Damage Length (in km): 0.510 km	Damages Location/Chainage:	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation : 20 MM mix seal surface done in 110 metre length.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : 75 MM WBM (Grill) & 20 MM Mix seal surface		
c)	Quality of Construction Material Used	S
Description of observation : Good quality		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	-
c)	Condition of railings/Slab/approach for Bridges	-
Description of observation of CD works : No provision in the scheme.		
Remark if any: Restoration work completed.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer:

Ram Prabesh Saw

Designation:

T.A, RWD
Work Circle Siwan.

12.7.21
(Signature)

13/7/21
AE