

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <i>Kadganwan - Khutti Hasilli</i>		
Hazards	Flood/Rain <i>Flood in 2020-21</i>	
Division : <i>Purnea</i>	District: <i>Purnea</i>	Actual Length (in km): <i>4.827</i>
Damage Length (in km): <i>0.010</i>	Damages Location/Chainage: <i>Approx 3.230 to 3.240</i>	
Name of Scheme/Programme:	<i>PMGSY</i>	
Status of Project:	Under Agreement/Out of Agreement <i>Ongoing Scheme (Not Completed)</i>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<i>S</i>
Description of observation : <i>In 10 m length PCC work done in 3'75 width having thickness 125 mm.</i>		
b)	Adequate Thickness of pavement layers constructed	<i>S</i>
Description of observation : <i>Below PCC surface WBM 80 III 75m and LSB 80 I done.</i>		
c)	Quality of Construction Material Used	<i>S</i>
Description of observation : <i>Quality of PCC and WBM 80 III is Satisfactory</i>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<i>S</i>
Description of observation : <i>No Undulation on Surface.</i>		
e)	Compaction of flanks/ slope & raincuts	<i>S</i>
Description of observation : <i>No rain cuts in flanks</i>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<i>-</i>
b)	Condition of Vent Clearance	<i>-</i>
c)	Condition of railings/Slab/approach for Bridges	<i>-</i>
Description of observation of CD works : <i>-</i>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<i>Satisfactory (S)</i>
---------------------------------------	-------------------------

Name of Officer: *Rana BROWN Kumar Singh*
 Designation: *Executive Engineer*
RWD, Regional Laboratory, Bhagalpur.

[Signature]
 (Signature) *11.03.2021*