

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Parmanandpur to Khutarrai

Hazards: Flood / Rain

Division: Madhepura

District: Madhepura

Actual Length (in km): 8.600 KM

Damage Length (in km): 0.187

+ Damages Location/Chainage: 0.150 KM - 0.157 KM, 0.900 KM - 0.964 KM, 1.950 KM - 1.996 KM, 2.100 KM - 2.133 KM, 2.450 KM - 2.470 KM, 3.700 KM - 3.717 KM

Name of Scheme/Programme:

Status of Project:

Under Agreement ☒ Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/U)

1.

Pavement (BT/CC)

BT

a)

Condition of Surfacing

S

Description of observation :

b)

Adequate Thickness of pavement layers constructed

S

Description of observation

c)

Quality of Construction Material Used

S

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship etc

—

Description of observation :

e)

Compaction of flanks/ slope & raincuts

—

Description of observation :

2

Cross Drainage Structure

N.A.

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab Gulzarbag, Patna

12/07/2021

12/07/2021