

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: Nirmali to Hariyahi via Jarauli

Hazards: Flood/Rain

Division: Supaul

District: Supaul

Actual Length (in km): 6.400

Damage Length (in km): 0.611

Damages Location/Chainage: 0.100KM - 0.320KM, 0.706KM - 0.716KM,

Name of Scheme/Programme:

Status of Project:

Under Agreement/Out of Agreement

0.889KM - 0.903KM, 1.812KM - 1.826KM,
2.210KM - 2.217KM, 2.700KM - 2.723KM,
2.800KM - 2.860KM, 3.040KM - 3.078KM &
3.180KM - 3.275KM

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

BT

a)

Condition of Surfacing

S

Description of observation :

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

c)

Quality of Construction Material Used

S

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

e)

Compaction of flanks/slope & raincuts

In Progress

Description of observation :

2

Cross Drainage Structure

NA

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

C)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab. Gulzarbag, Patna

10/07/2021

(Signature)