

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: MMGSY WERNI TO GARIGHUTTI		
Hazards	Flood/Rain	
Division: MANIHARI	District: KATIHAR	Actual Length (in km): 2.176KM
Damage Length (in km): 0.387KM	Damages Location/Chainage:	
Name of Scheme/Programme:	MMGSY	
Status of Project:	Under Agreement/Out of Agreement ☒	
Sr. No.	Parameters to be Checked in Restoration work	Remarks :
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N/A
Description of observation :		
e)	Compaction of flanks/slope & raincuts	S
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N/A
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: Work done found satisfactory.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: **KUMAR RAKESH**

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

10.07.21