

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: MANSAHI KURSEL PMGSY PATH TO MANSAHI AMIN NAGAR

Hazards Flood/Rain Flood/Rain

Division: MANIHARI District: KATI HAR Actual Length (in km): 1.373 KM

Damage Length (in km): 0.355 KM Damages Location/Chainage:

Name of Scheme/Programme: MMGSY

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : /
---------	--	-------------

1.	Pavement (BT/CC)	<u>S</u>
----	------------------	----------

a)	Condition of Surfacing	<u>S</u>
----	------------------------	----------

Description of observation :

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
----	---	----------

Description of observation :

c)	Quality of Construction Material Used	<u>S</u>
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	<u>N/A</u>
----	--	------------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	<u>-</u>
----	--	----------

Description of observation :

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	<u>N/A</u>
----	---	------------

b)	Condition of Vent Clearance	
----	-----------------------------	--

c)	Condition of railings/Slab/approach for Bridges	
----	---	--

Description of observation of CD works :

Remark if any: Work done found satisfactory.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

10.07.21