

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: KTR(PWD) MANIHARI ROAD TO DAGRA TOLA		
Hazards	Flood/Rain	
Division: MANIHARI	District: KATIHAR	Actual Length (in km): 1.433 km
Damage Length (in km): 0.530 km	Damages Location/Chainage:	
Name of Scheme/Programme:	MMGSY	
Status of Project:	Under Agreement Out of Agreement ☒	

Sr. No.	Parameters to be Checked in Restoration work	Remarks :
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	S

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
----	---	----------

Description of observation :

c)	Quality of Construction Material Used	S
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N/A
----	---	------------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	-
----	--	----------

Description of observation :

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N/A
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any: **Work done found satisfactory.**

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	----------

Name of Officer: **KUMAR RAKESH**

Designation: **तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना**

Signature
10.07.21