

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Singheshwar To Larkha

Hazards: Flood/Rain

Division: Madhepura

District: Madhepura

Actual Length (in km): 3.20

Damage Length (in km): 0.1918

Damages Location/Chainage: 0.500KM - 0.507KM, 0.5708KM - 0.5824KM

Name of Scheme/Programme:

Status of Project:

Under Agreement/Out of Agreement

0.700KM - 0.715KM, 1.100KM - 1.150KM
1.210KM - 1.214KM, 1.214KM - 1.230KM
1.230KM - 1.275KM, 1.300KM - 1.318KM
1.750KM - 1.759KM, 1.800KM - 1.804KM
Remarks: (S/U)

Sr. No.

Parameters to be Checked in Restoration work

1.

Pavement (BT/CC)

13T

a)

Condition of Surfacing

S

Description of observation :

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

c)

Quality of Construction Material Used

S

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

—

Description of observation :

e)

Compaction of flanks/ slope & raincuts

—

Description of observation :

2

Cross Drainage Structure

N.A.

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R.Lab, Gubarkha, Patna

11/07/2021

(Signature)