

(9)

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD		
Name of Scheme: Karnapur to Gandharain		
Hazards	Flood/Rain Flood	
Division: Jharkhand	District: Madhubani	Actual Length (in km): 5.350 km
Damage Length (in km): 0.166 km	Damages Location/Chainage:	
Name of Scheme/Programme:	F.D.R.	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC) CC	
a)	Condition of Surfacing	S
Description of observation: cc surface found in good condition		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation: Adequate Thickness found		
c)	Quality of Construction Material Used	S
Description of observation: Good quality of Material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	S
Description of observation: Found in good condition		
e)	Compaction of flanks/ slope & raincuts	
Description of observation: Flank work in progress		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	NA
b)	Condition of Vent Clearance	NA
c)	Condition of railings/Slab/approach for Bridges	NA
Description of observation of CD works: NA		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

19/7/21
AE

19/7/21
(Signature)

Scanned with CamScanner

Scanned by CamScanner