

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	Bhagat Singh To Domeghat		
Hazards	Flood/Rain		
Division :	Darbhaunga-1	District:	Darbhaunga
Damage Length (in km):	0.030	Actual Length (in km):	1.300
Name of Scheme/Programme:			
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)	CC	
a)	Condition of Surfacing	—	
Description of observation : The work has been not started			
b)	Adequate Thickness of pavement layers constructed	—	
Description of observation :			
c)	Quality of Construction Material Used	—	
Description of observation :			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—	
Description of observation :			
e)	Compaction of flanks/ slope & raincuts	—	
Description of observation :			
2	Cross Drainage Structure	N.A.	
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
C)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works :			
Remark if any: The work has been not started			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab, Guwahati, Patna

Signature

01/07/2021

Signature

20/07/20