

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme:	Sohma to Sukhagan Bandh		
Hazards	Flood/Rain		
Division : Rosera	District: Samastipur Actual Length (in km): 2.300		
Damage Length (in km): 0.600	Damages Location/Chainage:		
Name of Scheme/Programme:	FDR		
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		
a)	Condition of Surfacing		S
Description of observation : Good (PMC work)			
b)	Adequate Thickness of pavement layers constructed		S
Description of observation : M-SS. 20 mm thickness.			
c)	Quality of Construction Material Used		S
Description of observation : Satisfactory (PMC work)			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.		S
Description of observation : No defect- (PMC work)			
e)	Compaction of flanks/ slope & raincuts		
Description of observation : No provision			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
C)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works : No provision			
Remark if any: PMC work completed. Rest work:- 200 m C.C length (H.P.O)			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	U
---------------------------------------	---

Name of Officer: Mahesh Pd. Gupta.

Designation: EE, RWD, Regional Lab.
Purnea

(Signature) 23/7/2022