

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme:	Haganpur to Kate - Narpatnagar	
Hazards	Flood/Rain	
Division:	Rosera	District: Samastipur
Damage Length (in km):	2.70	Actual Length (in km): 9.10
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation :		
Good Condition		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
BT thickness - 20 cm		
c)	Quality of Construction Material Used	S
Description of observation :		
Satisfactory		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	S
Description of observation :		
No defect		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
No provision		
Remark if any:		
work done in good Condition		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Mahesh Pd. Gupta.

Designation:

EE, RWD, Regional Lab.
Purnea

(Signature)

MPK 23/07/2019