

| INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD |                                                                                                                                                       |                              |
|-----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| Name of Scheme:                               | Sakar Pura to Mahua Chapki                                                                                                                            |                              |
| Hazards                                       | Flood/Rain                                                                                                                                            |                              |
| Division:                                     | Rosera                                                                                                                                                | District: Samastipur         |
| Damage Length (in km):                        | 0.540                                                                                                                                                 | Actual Length (in km): 2.800 |
| Name of Scheme/Programme:                     | FDR                                                                                                                                                   |                              |
| Status of Project:                            | Under Agreement/Out of Agreement                                                                                                                      |                              |
| Sr. No.                                       | Parameters to be Checked in Restoration work                                                                                                          | Remarks: (S/U)               |
| 1.                                            | Pavement (BT/CC)                                                                                                                                      |                              |
| a)                                            | Condition of Surfacing                                                                                                                                | BT                           |
| Description of observation:                   |                                                                                                                                                       |                              |
| Good Condition                                |                                                                                                                                                       |                              |
| b)                                            | Adequate Thickness of pavement layers constructed                                                                                                     |                              |
| Description of observation:                   |                                                                                                                                                       |                              |
| Lower BT. thickness                           |                                                                                                                                                       |                              |
| c)                                            | Quality of Construction Material Used                                                                                                                 |                              |
| Description of observation:                   |                                                                                                                                                       |                              |
| Satisfactory                                  |                                                                                                                                                       |                              |
| d)                                            | Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. |                              |
| Description of observation:                   |                                                                                                                                                       |                              |
| NO defect                                     |                                                                                                                                                       |                              |
| e)                                            | Compaction of flanks/ slope & raincuts                                                                                                                |                              |
| Description of observation:                   |                                                                                                                                                       |                              |
| no provision                                  |                                                                                                                                                       |                              |
| 2                                             | Cross Drainage Structure                                                                                                                              |                              |
| a)                                            | Condition of head walls in Hume pipe culverts                                                                                                         |                              |
| b)                                            | Condition of Vent Clearance                                                                                                                           |                              |
| c)                                            | Condition of railings/Slab/approach for Bridges                                                                                                       |                              |
| Description of observation of CD works:       |                                                                                                                                                       |                              |
| NO Provision                                  |                                                                                                                                                       |                              |
| Remark if any:                                |                                                                                                                                                       |                              |
| Work done is in good Condition                |                                                                                                                                                       |                              |

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Mahesh P. Gupta.

Designation:

EE, RWD, Regional Lab -  
Munee

M.P. 23/07/2024  
(Signature)