

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Ram Sainia Pool to Warali Chowk Path

Hazards Flood/Rain

Division: Rosera District: Samashpur Actual Length (in km): 1.000

Damage Length (in km): 0.700 Damages Location/Chainage:

Name of Scheme/Programme: FDOR

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
---------	--	-----------------

1.	Pavement (BT/CC) <u>CC.</u>	
----	-----------------------------	--

a)	Condition of Surfacing	<u>S</u>
----	------------------------	----------

Description of observation :

Satisfactory

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
----	---	----------

Description of observation :

C.C. Pavement thickness - 160 mm

c)	Quality of Construction Material Used	<u>S</u>
----	---------------------------------------	----------

Description of observation :

Satisfactory

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
----	---	----------

Description of observation :

No defect

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation :

Flank work is to be required
(No Provision in the estimate)

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	
----	---	--

b)	Condition of Vent Clearance	
----	-----------------------------	--

c)	Condition of railings/Slab/approach for Bridges	
----	---	--

Description of observation of CD works :

No Provision

Remark if any: Flank work is to be required.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Mahesh Prasad Gupta.
EE, RWD, Regional Lab.
Purnea

Designation:

(Signature) 23/7/2024