

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Phaneshpur to Ganoul via Phorag Baza</u>		
Hazards	Flood/Rain	
Division: <u>Udakhungang</u>	District: <u>Mathepura</u>	Actual Length (in km): <u>2.765</u>
Damage Length (in km): <u>1.600</u>	Damages Location/Chainage:	
Name of Scheme/Programme:	<u>FDR</u>	
Status of Project:	Under Agreement/Out of Agreement <u>out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>
Description of observation: <u>20mm mix seal surface done in about 1.600 km length.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation: <u>20mm mix seal surface.</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation: <u>20mm mix seal surface good quality.</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>U</u>
Description of observation: <u>There are undulations at some places.</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation: <u>There is provision of E/W on both flanks in 1.60 km length. E/W in part length not completed.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>-</u>
b)	Condition of Vent Clearance	<u>-</u>
c)	Condition of railings/Slab/approach for Bridges	<u>-</u>
Description of observation of CD works: <u>No provision of CD works</u>		
Remark if any: <u>E/W in flank is not completed. In the estimate, Logo Board is sanctioned. But not found at site.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer:

Ram Prakesh Sah

Designation:

T. A.
R.W.D. works circle
Siwani.

23/7/21
AG.

23.7.21
(Signature)