

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30/7/21	District: Chapra Saran
Division : Chapra-2	Length (km): 1.38
Name of the Road: L031-TOT to Rampur (VRI9)	
Scheme/Programme: PMASy	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

**Observation Remarks:-** Some patch Developed in Road Somewhere  
This Road is out of 5 year maintenance period.

2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A.
c)	Condition of railings/slab/approach for Bridges	N.A.
d)	Condition of Vent Clearance	S

**Observation Remarks:-**

3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

**Observation Remarks:-**

4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	S

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Bindu Rajak  
Executive Engineer  
R.W.D.

Designature:-

Regional Leeb Darbhanga

30/07/21  
A.E.

(Signature) 30/7/21