

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30/7/2021		District: Saran
Division : Marauna		Length (km): 3.125
Name of the Road: Bansohi Basic school to Malah Toli Tak.		
Scheme/Programme: MMGSY (SC) Routine Maintenance		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Sri Kant Prasad
Name of Officer:-

Designature:- E.E.

Satisfactory (S)/ Unsatisfactory (U)

S

30/7/2021
A.E.

30/7/2021

(Signature)