INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 30 7 202 1	District: Saran	
Division: Maraura Length (km): 0.725			
Name of the Road: Ragendra Ogha Ke Cihar to Cihoghari Nadipul			
Scheme/Programme: MMG154 (Ger) Routine Maintenance.			
Sl. No.	Parameters to be	The state of the s	Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		5
b)	Riding Quality		S
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		_
e)	Contraction Joints provided or not (CC Pavement)		S
f)	Compaction of flank/slope & raincuts if any		S
Observation Remarks:-			
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		-
c)	Condition of railings/slab/approach for Bridges		
d)	Condition of Vent Clearance —		
Observation Remarks:-			
3.	Road Furniture		
a)	Whether sign boards/informatory/caus stones/Pavement road markings are pro-	tionary Board/ km & 200m ovided and maintained	· S
Observation Remarks:-			
,4			
4.	Compliance History	We have the second seco	
a)	Status of ATR's & any others		- No -
Overall Rating : Satisfactory (S)/ Unsatisfactory (U)			

Sn kant Prased.

Designature:- E-E

