## INSPECTION REPORT FOR ROUTINE MAINTENANCE

	inspection: 30 7 202   District: Saran Length (km): 1,75	
Division	: Marawa Length (km): 1, 75 the Road: Dumduma to Sheikhpura Porma	of School.
	Programme: MMGSY (SC) Routine Maintenau	
Sl. No.	Parameters to be checked	Remarks (S/U)
	Pavement	
1.		S
a)	Condition of Surfacing	S
b)	Riding Quality	* 5
c)	Road Camber  Whether free from defects such as visible cracks, exposed	
d)	aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
2.	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting	<u>.</u> S
2. a) b)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts	. S
a)	Condition of head walls in Hume pipe culverts including its painting	-
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance	_ S
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges	-
a) b) c) d)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance	-
a) b) c) d) Observ	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  vation Remarks:-	-
a) b) c) d) Observ	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  vation Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m	- - S
a) b) c) d) Observed 3.	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  ation Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	- - S
a) b) c) d) Observed  3. a)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  vation Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained  vation Remarks:-	- - S

Sin Kant Praved.

Designature:- E.E.

Satisfactory (S)/ Unsatisfactory (U)

(Signature)