

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29.07.2021		District: Muzaffarpur	
Division : Muzaffarpur West		Length (km): 0.733 km	
Name of the Road: Loss Banka Gaon To Banka Gaon South Tola (V.R-12)			
Scheme/Programme:		Routine Maintenance	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement C.C.	
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Pot developed in C.C. surface & exposed aggregate in C.C. 550 M to 600 M, 400 to 430 M, 500 to 1000 M.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A
Observation Remarks:- N.A		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture Informative Board, KM Board & 200m stones are provided in Road		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Rakesh Paswan

Designature:- E. E

ABH
29-07-2021
AB

29/7/21
(Signature) E. E