

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29.07.2021	District: Muzaffarpur
Division : Muzaffarpur West	Length (km): 1.18 km
Name of the Road: L105-Tor N Bheriyahi (VR 16)	
Scheme/Programme: Routine Maintenance under P.M. & S.Y.	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

In Flank Subs → Buses are developed partially.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	S

Observation Remarks:-

C.D is in good condition

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

Road Furniture Informatory Board Maintenance Board, K.M. & 200m P.M. is found in good condition

4.	Compliance History	
a)	Status of ATR's & any others	—


Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Ramesh Paswan

Designature:- E. E.


 29.07.2021
 AR


 29.7.21
 (Signature) E. E.