

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - Katta / Palsaul Rajghat to Lakhanpur Path

☒ A. For Road

1. Damage Location/Chainage : 0.005 km to 0.286 km, 0.500 km, 0.800 km, 0.900 km, 1.00 km, 1.29 km
2. Damage Length : 0.986 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick ball
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.986 km

☒ B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


Signature

(Name of Inspector)

EE

RWD work Division

Muzaffarpur East - I

GENERAL ABSTRACT

Name of Road Pahsaul Rajghat to Lekhanpur Path

District Muzaffarpur

Block Katra


Division Muzaffarpur East-2


Length of Road (in Km)


1.450 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	15.832
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	15.832
TOTAL COST OF PROJECT IN LACS =		15.832


say 15.83 lac


JE
RWD


AE
RWD


EE
RWD

Technically approved for Rs 15.83 lac
(Rupees fifteen lac eighty three thousand only)


SE

RWD WORKCIRCLE
MUZAFFARPUR