

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhalekar

2. Name of Block/Road - Kakra / Bhadai Chok to Phanor high school.

A. For Road

1. Damage Location/Chainage : 0.01km, 0.100km, 0.150km, 0.350km, 0.408km, 0.455km, 0.600km
2. Damage Length : 0.336km (0.335km)
3. Nature of Damage : approx
4. Details of Restoration Works :
 - i. Material being used in Restoration works : stone boulders
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.336 km approx
(0.335 km)

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
21.11.20
Signature

(Name of Inspector)

EE

RWD WORK DIVISION
MUZAFFARPUR CANT-1

GENERAL ABSTRACT

Name of Road Bhadai Chowk to Dhanor High School

District Muzaffarpur

Block Katra


Division Muzaffarpur East-2


Length of Road (in Km) 3.476 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.381
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.381
TOTAL COST OF PROJECT IN LACS =		4.381


say 4.38 lakh


JE
RWD


AE
RWD


EE
RWD

Technically approved for Rs 4.38 lakh
(Rupees four lakh thirty eight thousand) only


SE
RWD WORK CIRCLE
muzaffarpur