

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Aurai / 1078 Pmasy road nunnu house to Tonky Khurd (VR44)


(A) For Road:

1. Damage Location/Chainage :- 0.400km, 0.600km, 0.700km
2. Damage Length :- 0.12192km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.12192km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road L078 PMGSY Road Nunu House to Jonky Khurd (VR44)

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km) 1.158 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	3.666
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	3.666
TOTAL COST OF PROJECT IN LACS =		3.666

Sus
11/11/21
JE
RWD

AN 11/11/21
AE
RWD

Gay
11/11/21
EE
RWD

Technically approved for Rs 3.666 lac
(Rupees three lac sixty six thousand six hundred only)

11/11/21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर