Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: Gyan VI blakar 2 Name of Block/Road: makerand bur to kessuri (agignat) (A) For Road:~ 1. Damage Location/Chainage :- 0.100km, 0.250km, 0.50km, 0.70km, 2.5km. (Leyte= 6.10 m) :- 214.0 M. 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: Material being used in Restoration works:- Brick bots-(i) Equipment's/Tools being used in Restoration works:-(ii) Procedure taken up in Restoration works: (iii) :- 0.214km Restored Length (iv) ✓ (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-

Signature of JE/AE/EE

(iv) Restored Length

(iii) Procedure taken up in Restoration works:-

Signature

(Name of Inspection)

EE

PWD WORK DIVISION

M429 HAXPUX ECYL-L

GENERAL ABSTRACT

Name of Road

Makradhpur to Khajari

District

Muzaffarpur

Block

Gaighat

Division

Muzaffarpur East-2

Length of Road (in Km)

6.100 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.003
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.003
TOTAL C	OST OF PROJECT IN LACS =	4.003

Say 3 = 4.00 lac

JE RWD

× 111120

ΑE

RWD

EE

RWD

Technically Approved for Ps 4.00 lac (pupees four lacs only).

Rup work direle