

BAD Path Sahani Chak to Unaristhahadit to Lemin Nagar (P.P.O)

Schedule XLV-Form No. 134

SHANSHARPUR

DIVISION

LAKHNAR

SUB-DIVISION

1737

MEASUREMENT BOOK


INDES

PAGE

प्रमाणित किया जाता है की इस
मापी-पुस्त में मशीन द्वारा उतकित
100 पन्ने है जो की श्री मुकेश
कुमार सिंह, सहायक उन्निधन्ना
लखनौर के निगित किया जाता है !



कार्यपालक
ग्रामीण कार्य विभाग
झंझारपुर


02/12/21

INDES

PAGE

Name of work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

1

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH- F.P.R.					
Name of Work - Mortar & Flood					
damage road & som					
PWP PATH Sahani chaulc					
Umari to Madadali tal					
Under F.P.R.					
Agency - Departmental					
Authority - S.E. P.W.D. Circle -					
Ltr No. 734 (W.E.)					
dt. 04/05/21					

Work period - 25/09/20 to 06/10/20

Date of measurement - 17/10/20

Date of report - 06/05/21

(1) Providing and filling

(1) Cost of embankment with

approved material obtained

from borrow pit with

load up to 1000 M.

CH - 150-200M - 2x 300.00 x 1.50 x 1.50 = 1350.00 M³

at 1350.00 M³ @ 173.20/M³ = 233685.00

(2) Providing and filling

brick batts and stakes

damage embankment

including cost of brick

Continuation

work at viderb No -
024 P = $\frac{22}{2}$ tott 17/10/20
ventized and talnd
correct

10/5
OF

~~10/5~~

Continuation