## **Inspection Report for Flood Damage Work**

Date:-				
1 Name of PIUs: - Gyan Vi	Shakar			
2 Name of Block/Road :-	Harkiniya	dalderi to	Ram port	pay 1ce mark vi
(A) For Road:				75.000
3. Nature of Damage	:- 5°5-000	•		
(i) Material being used in Re	estoration works	- Brich ba	5, Hum	~ bip~
(ii) Equipment's/Tools being	used in Restorat	tion works:-  🍞	actor,	1 (0
(iii) Procedure taken up in Re	storation works:			

:- 55.00m

## (B) For Bridge:

(iv)

Damage Location/Chainage : Damage Length : Nature of Damage : Details of Restoration Works :-

Restored Length

- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature Signature

(Name of Inspection)
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

## **GENERAL ABSTRACT**

Name of Road

Harhiriya Laldevi to Ramprit Das Ke Math Via Banua

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

1.087 Km

	DESCRIPTION	AMOUNT (LAKHS)
SI. No.	DESCRIPTION	14.103
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.349
4	H.P.	14.452
	GRAND SUB TOTAL	14.452
TOTAL C	OST OF PROJECT IN LACS =	

Say 14.45 lac

JE

RWD

ΑE

RWD

EE

DWD/

Technically approved for RS 14.45 lac (Rupeel fourteen lac forty five thousand only)

RWD WOON COOLL